Galveston District Safety Briefing February 6, 2014

Jason Shreve, GSP, OHST

Safety Specialist

US Army Corps of Engineers
BUILDING STRONG®

Review of FY '13 Dredging Accidents



FY '14 Dredging Accidents to date

2014 Recordable Accident Causes



EM 385-1-1 Update

- New revision coming soon.
- Revision has been delayed due to illness of project champion.
- No extract date of release set at present.

Future EM 385-1-1 Changes

- 19.G.03 (4) c. Pipelines shall be marked with the owner's name for positive identification in the event of loss (adrift) or damage to vessels operating in the area.

Future EM 385-1-1 Changes

- 19.G.09 d. Amphibious excavators will only be operated in accordance with the manufacturer's operating instructions. A copy of the operator's manual will be readily available on the equipment.

Future EM 385-1-1 Changes

- Changes to guidelines for disposal site shelters (Dump Shacks.)
  - ►New lighting requirements
  - ►Minimum size restrictions
  - ►Water, Heating and Storage requirements
  - ►Fire Extinguisher requirements.

Questions?